



## Surface Scratches

Removal of surface scratches on a counter finished with Bizz Polymerized Oil



### Tools and materials required to restore your Bizier countertop



Polymerized Oil



Sanding Block



Orbital Sander



Sand Paper. Steel Wool



Soft Cloth

Using the sanding block with 150 grit sandpaper, sand the area to be restored, in the direction of the wood grain, until scratches disappear. If the scratches are still visible, use an orbital sander with 120 grit paper. After having removed scratches, sand, in the direction of the wood grain, with 150 grit paper on the sanding block. Wet the sanded area and let it dry. Lightly sand the surface again with 180 grit sandpaper. As soon as the surface is smooth, stop sanding. Remove dust with a vacuum cleaner. Apply a coat of polymerized oil with a soft cloth. Wait 15 minutes then wipe and polish vigorously with 0000 steel wool. Wipe again with a clean cloth. It is very important to wipe off all oil not absorbed in the wood. Excess oil will form a sticky layer on the surface. If this happens, repeat the steps from the beginning.

We recommend that you wait at least three months before restoring the surface of a new counter. The counter must adapt to your environment and your work habits. Remember that a counter finished with Bizz™ beeswax or oil is very easy to restore, so do not be alarmed if your counter has scratches.

#### CAUTION:

- Rags soaked in oil are flammable. Immerse your rags in water before disposal.
- Polymerized oil contains tung oil and may cause an allergic reaction to people allergic to nuts
- Water or other liquids should not be left to stagnate (for example overnight) under a rubber mat or cutting board. Rags or wet towels left to dry on the counter are also to be avoided.
- Sources of intense heat such as hot pans or small appliances that emit heat, should be kept away from wood countertops

